

## STATE OF TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION CHATTANOOGA ENVIRONMENTAL FIELD OFFICE **DIVISION OF WATER RESOURCES**

**540 MCCALLIE AVENUE, SUITE 550 CHATTANOOGA, TN 37402** 

**STATEWIDE 1-888-891-8332** PHONE 423-634-5745

FAX 423-634-6389

dsol Co. A. Complex 2017

August 23, 2012

Mr. Tim Huddleston W & O Construction 150 Construction Drive Livingston, TN 38570

Subject:

NPDES Construction General Permit Tracking No. TNR111881

Southeastern Tennessee State Regional Correctional Facility (also known as

**Bledsoe County Correctional Complex**)

State of Tennessee - Department of Finance and Administration

Pikeville, Bledsoe County, Tennessee

Dear Mr. Huddleston:

An inspection of the sediment and erosion controls for the above mentioned project was conducted by Micah Gravitt of the Chattanooga Field office on 08/22/12. During the inspection, problems with your erosion controls were noted and documented on the enclosed inspection form. Please read these notes and correct these problems on site as soon as possible. Your cooperation in this matter is appreciated. If you have any questions, please contact Micah Gravitt at (423) 634-2547 or by E-mail at Micah, Gravitt@tn.gov .

Sincerely:

Jennifer Innes

Asst. Water Pollution Manager

Chattanooga Environmental Field Office

Enclosure: Inspection Form

Site Photographs

CC:

DWPC, Chattanooga EFO Permit File




## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION


Division of Water Resources 6<sup>th</sup> Floor Annex, L&C Tower, 401 Church Street, Nashville, Tennessee 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

C 45		on Ctata T	logional Car	readi.	mal F	acility (alec				WMD111001
Site/Project Name: Southeastern Tennessee State Regional Correctional Facility (also known as Bledsoe County Correctional Complex)  Street Address or 1045 Hersehead Road						NPDES	NPDES Tracking Number:		TNR111881	
						Start d	Start date:		24-MAY-11	
Location: 1045 Horsehead Road							Estima	Estimated end date:		24-JUL-12
Site Construction of a wastewater treatment plant with all parking, roads,					Latitud	Latitude (dd.dddd):		35.7375		
Description: utilities and storm water system.						Longitu	Longitude (-dd.dddd):		-85.25	
DEC. Chatters See MS4			MS4			Acres I	Acres Disturbed:		9	
			Jurisdiction	liction:			Total A	Total Acres:		
Name of Permittee (Develop	er/Operator): St	ate of Ten	nessee - Dep	artme	nt of F	Finance and	Administration			
			dleston@wocc.com				<b>Contact Phone:</b> 931-403-5311			
Address: 150 Construction Drive City			City: Livin	City: Livingston				ΓN	<b>Zip:</b> 3857	0
Check List (office & field check				Yes	No			Comment	s	
I GOD				$\boxtimes$						
Does the site have CGP coverage?  Is NOC posted on site?				Ø						
Have the site contractors signed the NOI?				Ø						
			Ħ	m			N/A			
				X						
Are EPSCs in accordance with SWPPP?				H	A			9		
6 Are EPSCs installed properly and functional?			H	H			N/A			
7 Are inspection reports available on site?				Ħ	H					
8 Is the proper buffer zone maintained?				X	H		Λ			
9 Inactive areas stabilized in 15 days? (7 days for steep slopes?)				H						
10 Are more than 50 acres disturbed at one time?			片	HH						
11 Has sediment discharged off site?				X	ዙ					
		12 Has sediment discharged into waters of the State?				1				
					片片	-				
13 Are there unauthorized	alterations to wat	ers of the	State?	H	×					
Are there unauthorized a Are there violations of a	alterations to wat	ers of the	State?							
Are there unauthorized Are there violations of a If so, ARAP No.?  Other pollutants/dischar  General Comments:Sedimen	alterations to wat an existing ARAF rges or unusual pr t has migrated in	roblems?	Creek. The s	sedime	ent de	n aciion. <i>A</i>	ISO, LEHROYE ALL	Y ULLUL SUUIII	TOTHE GLOBOUR	U NOLU II VALU
Are there unauthorized  Are there violations of a  If so, ARAP No.?	alterations to wat an existing ARAF rges or unusual pr t has migrated in	roblems?	Creek. The s	sedime	ent de	n aciion. <i>A</i>	ISO, LEHROYE ALL	Y ULLUL SUUIII	TOTHE GLOBOUR	U IOULU II VALU
Are there unauthorized: Are there violations of a If so, ARAP No.?  Other pollutants/dischar General Comments:Sediment remove the sediment as so existing silt fencing. Repair	alterations to wat an existing ARAF rges or unusual pr t has migrated in on as possible to ir or replace the	roblems?	Creek. The s sible future ng near Mill	sedime enfor	ent de cemen k that	n aciion. <i>A</i>	ISO, LEHROYE ALL	Y ULLUL SUUIII	ediment dis	U NOLU II VALU
Are there unauthorized: Are there violations of a If so, ARAP No.?  Other pollutants/dischar General Comments:Sediment remove the sediment as soc existing silt fencing. Repair	alterations to wat an existing ARAF rges or unusual pro- it has migrated in on as possible to ir or replace the	roblems?	Creek. The s	sedime enfor	ent de cemen k that	n aciion. <i>A</i>	ompromised lea	ding to the s	ediment dis	scharge.
Are there unauthorized: Are there violations of a If so, ARAP No.?  Other pollutants/dischar General Comments:Sedimen remove the sediment as soc existing silt fencing. Repair	alterations to wat an existing ARAF rges or unusual properties of unusual properties of unusual properties of the contract of	roblems?	Creek. The sible future ng near Mill	sedime enfor	ent de cemen k that	has been c	ompromised lea	ding to the s	ediment dis	scharge.
Are there unauthorized: Are there violations of a If so, ARAP No.?  Other pollutants/dischar General Comments:Sedimen remove the sediment as soc existing silt fencing. Repair	alterations to wat an existing ARAF rges or unusual properties of unusual properties of unusual properties of the contract of	roblems? nto Mill C avoid pos silt fencir	Creek. The sible future ng near Mill	sedime enfor	ent de cemen k that	has been c	Follow Up	ding to the s	Tern	nination Date:
Are there unauthorized of the Are there violations of a lif so, ARAP No.?  Other pollutants/dischargement as soo existing silt fencing. Repair Routing Con-Site Contact (if available)  TDEC Personnel/Information	alterations to water an existing ARAF rges or unusual property that migrated in on as possible to ir or replace the	roblems? nto Mill C avoid pos silt fencir	Creek. The sible future ng near Mill	sedime enfor	ent de cemen k that	has been c	Follow Up	ding to the s	Tern	Date:
Are there unauthorized: Are there violations of a If so, ARAP No.?  Other pollutants/dischar General Comments:Sedimen remove the sediment as soc existing silt fencing. Repair	alterations to water an existing ARAF rges or unusual property that migrated in on as possible to ir or replace the	roblems? nto Mill C avoid pos silt fencir	Creek. The sible future ng near Mill	sedime enfor	ent de cemen k that	has been c	Follow Up	inding to the s	Tern  EFO: Nam  Chat	nination Date:



Photograph 1: Remove the sediment deposits from the stream using hand tools only.



Photograph 2: Repair/replace silt fencing that has been undercut and remove all sediment deposits existing below the silt fencing located within the rip rap area. Areas of bare soil below the silt fencing can be stabilized in place with seed and straw.